

TEP
RMV 38-17
Location # 335271



location



location

TEP
RMV 38-17
Location # 335271



location



location

TEP
RMV 38-17
Location # 335271



Lack of stabilization/ compaction



Lack of stabilization/ compaction

TEP
RMV 38-17
Location # 335271



Tunneling through berm



Tunneling through berm

TEP
RMV 38-17
Location # 335271



Tunneling through berm



Glycol vessel missing labeling