

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/04/2021

Submitted Date:

11/08/2021

Document Number:

695105090

FIELD INSPECTION FORM
 Loc ID 333534 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217810	WELL	SI	08/01/2021	GW	071-06589	CHINAMANS CANYON 24-19	SI
263628	PIT	AC	05/13/2002		-	CHINAMANS CANYON 24-19	AC
270338	WELL	PR	12/29/2004	GW	071-07941	CHINAMANS CANYON 24-19 TR	PR
278527	PIT	AC	06/24/2005		-	CHINAMANS CANYON 24-19 ONSITE	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	PHOTO 2: TR WELL NAME DOES NOT MATCH WELL NAME ON FILE WITH COGCC (IT DOES NOT MATCH ON FORM 2). PHOTO 3: ORIGINAL WELL NAME DOES NOT MATCH WELL NAME ON FILE WITH COGCC (IT DOES NOT MATCH ON FORM2).		
Corrective Action:	Install sign to comply with Rule 605.a. CA DATE 2/8/2021.	Date:	02/08/2022

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	PHOTO 4: VEGETATION AROUND WELLHEAD IS NOT MAINTAINED.		
Corrective Action:	MAINTAIN VEGETATION AROUND WELLHEAD AND LOCATION PER RULE 606.	Date:	11/19/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Progressive Cavity	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 217810 Type: WELL API Number: 071-06589 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: WELL LAST PRODUCED JULY 2021

Corrective Action: _____ Date: _____

Facility ID: 263628 Type: PIT API Number: - Status: AC Insp. Status: ACFacility ID: 270338 Type: WELL API Number: 071-07941 Status: PR Insp. Status: PR**Producing Well**

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 278527 Type: PIT API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 263628Lat: 37.238262Long: -104.715645Reference Point: SEOther: Length: 50Width: 40**Lining:**Liner Type: Liner Condition: Comment: Corrective Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: NONECorrective Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date: Type: Produced WaterLined: NOPit ID: 278527Lat: 37.238262Long: -104.715645Reference Point: SEOther: Length: 60Width: 30**Lining:**Liner Type: Liner Condition: Comment: Corrective Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition:

Inspector Name: Beardslee, Tom

Comment:	NONE	Date:
Corrective		
Anchor Trench Present: <u>NO</u> Oil Accumulation: <u>NO</u> 2+ feet Freeboard: <u>YES</u>		
Comment:		Date:
Corrective		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402864275	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5574517