

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/08/2021

Submitted Date:

11/08/2021

Document Number:

701102174

FIELD INSPECTION FORM

Loc ID 315342 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 760 HORIZON DRIVE STE 400
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box
Thompson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230661	WELL	PR	07/13/1979	GW	103-08329	FEDERAL 33-3	PR

General Comment:

[COGCC Routine Inspection Report Summary](#)
Location is in a High Priority Habitat Area.
During this inspection the following compliance issues were observed:

- Tank battery sign not at tank battery.
- Storm water rill running off location into road ditch. Ditch from location to main road needs maintained.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location					
Lease Road:					
Type	Access				
comment:	Roadside ditch needs maintained.				
Corrective ActionL					Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	BATTERY				
Comment:	Tank battery sign not at tank battery.				
Corrective Action:	Install sign to comply with Rule 605.e.				Date: 02/15/2022
Emergency Contact Number:					
Comment:	911				Date:
Corrective Action:					Date: _____
Good Housekeeping:					
Type	TRASH				
Comment:					
Corrective Action:					Date:
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Bradenhead	# 1				corrective date
Comment:					
Corrective Action:					Date:
Type: Horizontal Separator	# 1				
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked	# 3				
Comment:					
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	30 bbl
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 230661 Type: WELL API Number: 103-08329 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Ditches	Fail			
Berms						
Gravel						

Comment: Storm water rill running off location into road ditch. Ditch from location to main road needs maintained.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/24/2021

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective

Date:

Fencing:

Fencing Type: Fencing Condition:

Comment: none

Corrective

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: At meter shed

Corrective

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402865655	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5575782
701102178	Inspection 701102174 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5575774