

Inspection Photos
Operator: Simcoe
API: 067-08852
Date: 11/17/2021



Photo 1. View of the project area from the well pad entrance facing center.




Photo 2. View of Russian thistle debris around facilities, needs to be removed.



Photo 3. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing in portions with western wheatgrass, sand dropseed, and crested wheatgrass.



Photo 4. View of open pipes within the eastern project area, need to be filled/covered.



Photo 5. View of what appears to be landowner equipment and debris stored within the northwestern corner of the well pad.



Photo 6. View of reference area comprised of irrigated grass and alfalfa field, as well as non-irrigated field, largely fallow at this time.