

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2021

Submitted Date:

11/29/2021

Document Number:

700703585

FIELD INSPECTION FORMLoc ID 314851 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|-----------------------------|---------------------|
| operating, 31 | | kfreeman@31operating.com | |
| , COGCC | | mike.leonard@state.co.us | |
| , COGCC | | kelly.rosenberg@state.co.us | regulatory/hearings |
| Thomson, Bud | | BLThomps@BLM.gov | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 229756 | WELL | SI | 10/01/2020 | GW | 103-07413 | GOVERNMENT 2-34 | SI |

General Comment:**COGCC Inspection Report Summary**

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

On Tuesday 11/23/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at 31 Operating Gov't #2-34, at Location # 314851 in Rio Blanco county Colorado.

While there, I observed no production operations. Well is shut in. All meters have been not calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. There is no evidence of tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. No evidence of tracking control BMP's.
2. Location and access shows signs of lack of stabilization and erosion. Sink hole is present along with some riling.
3. Cut slope shows signs of lack of stabilization with vegetation roots being exposed along with riling.
4. Locations weeds have turned into debris throughout location.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|------------|-------|--|
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--------------------|-------------|
| Comment: | 1-800-209-9762/911 | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | DEBRIS | | |
| Comment: | Locations weeds have turned into debris throughout location. | | |
| Corrective Action: | Remove all debris | Date: | 12/31/2021 |

Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|-----------------------------------|--------------------------------------|-------|-----------------|
| | | | corrective date |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Chemical tank in plastic containment | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-------------------------------|--|-------|
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | Well head not on plunger lift | | |
| Corrective Action: | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected FacilitiesFacility ID: 229756 Type: WELL API Number: 103-07413 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 9/2020

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Fail | Compaction | Fail | | | |

Comment: 1. No evidence of tracking control BMP's.
 2. Location and access shows signs of lack of stabilization and erosion. Sink hole is present along with some riling.
 3. Cut slope shows signs of lack of stabilization with vegetation roots being exposed along with riling.

Corrective Action: Provide proof of tracking control BMP's and Install or repair required BMPs

Date: 12/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402881847 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591164 |
| 700703597 | Photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591151 |