

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2021

Submitted Date:

11/29/2021

Document Number:

701600474

**FIELD INSPECTION FORM**

Loc ID 312326 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10160

Name of Operator: ENERGY INVESTMENT PARTNERS LLC

Address: P O BOX 225878

City: DALLAS State: TX Zip: 75222

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	Engineering
FLOURNOY, BOB	214-978-2500	bobflournoy@att.net	
Lindley, Trent		trent.lindley@state.co.us	NOAV
Quint, Craig		craig.quint@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279267	WELL	TA	12/15/2016	OW	075-09347	GIACOMINI 1	TA

**General Comment:**

Follow-up FIR from Doc. 699600175 dated 02/04/2020. Corrective Actions remain unresolved as of date of this FIR. Last MIT performed on 03/15/2013 Doc#200373764. Well required MIT performed prior to 03/15/2018. Well remains in TA status with no O&G activity observed. Equipment remains on location, access road is grown over.  
**NOTE TO OPERATOR:** Contact COGCC Engineering for directives.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Lease road mainly grown over, access off Logan County Road 54		
Corrective Action:	Repair and maintain lease road to comply with Rule 204 requirements.	Date:	11/29/2021

Overall Good: ☐

Emergency Contact Number:	
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
Date:	<input type="text"/>

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 0		
Comment:	Production equipment remains on location. No change in inventory.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 279267 Type: WELL API Number: 075-09347 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last MIT performed on 03/15/2013 Doc# 200373764 indicating well is past due for (5) yr. MIT. Well required a MIT on or before 03/15/2018. Well is (44) months past due on (5) yr. MIT Operator was notified of well issues on 02/04/2020 Doc#699600175.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Past Due MIT - Well is (44) months past due for (5) yr. MIT - Well remains TA	schureky	11/29/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402881356	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5590798">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5590798</a>