

Inspection Photos

API: 071-08046

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08046 | Date: 12/9/2021

Inspection Photos



Photo 1. Facing southeast along the access road. The culvert along the road is filled in with sediment. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 12/9/2021

Inspection Photos



Photo 2. Facing west toward the access road near the location. The road was graded where vehicle rutting has occurred. There is disturbance shown in the bottom left of the photo that needs to be seeded and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 12/9/2021

Inspection Photos



Photo 3. The rock check dam at red arrow is not properly installed. There is loose gravel that needs to be compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 12/9/2021

Inspection Photos



Photo 4. Facing west along the access road at the location. There was disturbance that has occurred in this area which needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 12/9/2021

Inspection Photos



Photo 5. Facing southwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08046 | Date: 12/9/2021