

Inspection Photos

Loc ID: 334229

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/9/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334229 | Date: 12/9/2021

Inspection Photos



Photo 1. There is a metal building along the access road where oil and gas vehicles parked off the designated road way blocking this building. This area has not been restricted to prevent access.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334229 | Date: 12/9/2021

Inspection Photos



Photo 2. The access road has been regraded however there are steep areas with insufficient gravel and stabilization. The red arrow points to a culvert that was damaged from grading. Lat/Long:37.23640,-104.69944. There is also a rock piled up on the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334229 | Date: 12/9/2021

Inspection Photos



Photo 3. The culvert was damaged which can puncture a tire. This needs to be repaired. There is sand and gravel filling into the opening of the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334229 | Date: 12/9/2021

Inspection Photos



Photo 4. This steep area of the road was regraded however there is now loose soils shown by shovel. This area needs to be stabilized (e.g. gravel, road base). There is also an exposed wire at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 334229 | Date: 12/9/2021

Inspection Photos



Photo 5. Facing north at the location.

