

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/08/2021

Submitted Date:

12/10/2021

Document Number:

693803899

**FIELD INSPECTION FORM**

Loc ID 316872 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10453  
Name of Operator: PARADOX UPSTREAM LLC  
Address: 500 DALLAS ST SUITE #1650  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Hankins, Neil	970-428-2742	davidh@paradoxresources.com	All Inspections
Nowak, Scott	713-899-0259	scottn@bogresources.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288131	WELL	PR	03/01/2020	GW	113-06226	HC FED 30-23-45 14	PR

**General Comment:**

COGCC staff performed a routine field inspection on 12/8/2021.  
Issues were found requiring corrective action. See inspection text and photos for details.  
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:
Type	Main		
comment:			
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	435-587-2237 or 911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Produced water tank inside metal berms is rusted out.		
Corrective Action:	Comply with Rule 606		Date: 03/11/2022
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		38.123148,-108.456480
Comment:	Tank rusted out. See Housekeeping section for corrective action.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	100 BBLs	STEEL AST		38.123504,-108.456582
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	Fresh water
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	100 BBLs	STEEL AST		38.123790,-108.456466		
Comment:							
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
<b>Venting:</b>							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
<b>Flaring:</b>							
Type							
Comment:							
Corrective Action:						Date:	

**Inspected Facilities**

Facility ID: 288131 Type: WELL API Number: 113-06226 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger lift](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402895768	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5603916">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5603916</a>
693803900	Inspection photos 12/8/2021	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5603909">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5603909</a>