

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/22/2021

Submitted Date:

12/30/2021

Document Number:

693700905

FIELD INSPECTION FORM

Loc ID 444471 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96155
Name of Operator: WHITING OIL & GAS CORPORATION
Address: 1700 LINCOLN STREET SUITE 4700
City: DENVER State: CO Zip: 80290

Findings:

- 2 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Smith, Sydney		ssmith@fundareresources.com	
Wheeler, Steven		steven.wheeler@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480257	SPILL OR RELEASE	AC	10/15/2021		-	Razor 25P	EI
480867	SPILL OR RELEASE	AC	10/15/2021		-	Razor 25P	EI

General Comment:

Inspected Facilities

Facility ID: 480257 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Facility ID: 480867 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)
Oily Soil	Piles	Adequate	
Comment	Impacted material is stockpiled on the location within bermed, lined area. Stockpile is approximately 60'x30'x6' or 400 cubic yards.		
Corrective Action	Submit waste disposal documentaiton on Form 27 Supplemental prior to or concurrent with closure request.		Date: 01/31/2022

Spill/Remediation:

Comment:	<p>Two spills (480257&480867) are unresolved at the Razor 25P pad at the same flowline excavation, listed under Whiting Oil and Gas. Unresoved Remediation Project #20870 is open to complete the site investigation. Excavation remains open on location and confirmation soil sample results have not been received.</p> <p>Remediation of both spills has created additional impacts to vegetation east of the spill area and original location. Operator has opened new entrance to Razor 25P pad as a result of spill remediation interfering with original pad entrance.</p> <p>At least one flowline is cut/out of service and unsupported in excavation. Operator should contact Engineering Integrity Group for direction regarding repairs.</p>	
Corrective Action:	<p>Operator should submit Form 19 Supplemental for both open spills with root cause analysis on flowline failure.</p> <p>Operator should submit Form 27 Supplemental with analytical results or schedule for obtaining results.</p> <p>Operator should submit Form 27 Supplemental with reclamation plan for impacts to surface outside working pad surface.</p>	Date: 01/31/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402913479	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5621463
693700906	Razor 25P Photos 12-22-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5621443