

Inspected Facilities

Facility ID: 420173 Type: WELL API Number: 123-32488 Status: SI Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC inspection followup to Remediation Project #17242 for facility closure. Operator has submitted initial data with elevated pH in sample results. Operator will submit additional data with Reclamation Plan pursuant to Rule 915.b.
 COGCC observed that dump lines and flowlines remain in place and are not properly abandoned at the time of inspection.

Corrective Action: Operator will submit Form 27 Supplemental with Reclamation Plan Operator will provide additional field screening and photographic documentation of any additional excavations conducted to remove flowlines and dump lines. Operator will also provide confirmation that dump lines and flowlines were removed pursuant to Rule 1105. Date: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402913482	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5621466
693700912	ChalkBluffs36-13H Photos 12-22-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5621446