

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/07/2022

Submitted Date:

01/07/2022

Document Number:

701102488

**FIELD INSPECTION FORM**

Loc ID 312507 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim	970-712-0099	mrinc20@maralexinc.com	<a href="#">Operations Manager</a>
Hahn, Travis		thahn@maralexinc.com	<a href="#">All Inspections</a>
Byers, Jim		jbyers@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221808	WELL	TA	01/01/2021	GW	077-08410	FEDERAL 25-3	TA

**General Comment:**

Inspection and Plugging Operation  
Inspector traveled to location 01/07/2022 to witness plugging operations base on Form 42 doc # 402918310 START OF PLUGGING OPERATIONS. Notice gave beginning date of 01/07/2022. No rig or personel on loction at time of arrival. No Communication made of delay or reschedule. No form 42 update made.  
Well last produced prior to January 1999. No MIT on record.

Location				
<b>Lease Road:</b>				
	Type	Access		
	comment:	Road poor condition.		
	Corrective Action			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
	Type	WELLHEAD		
	Comment:			
	Corrective Action:			Date:
<b>Emergency Contact Number:</b>				
	Comment:	911		Date:
	Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
	Comment:			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
	Type	WELLHEAD		
	Comment:			
	Corrective Action:			Date:
<b>Venting:</b>				
	Yes/No	NO		
	Comment:			
	Corrective Action:			Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:			Date:	

**Inspected Facilities**

Facility ID: 221808 Type: WELL API Number: 077-08410 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced prior to January 1999. No MIT on record.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well within two years of the initial shut-in date. Preform MIT on well. Date: 04/25/2021

**Workover**

Comment: Inspector traveled to location 01/07/2022 to witness plugging operations base on Form 42 doc # 402918310 START OF PLUGGING OPERATIONS. Notice gave beginning date of 01/07/2022. No rig or personel on loction at time of arrival. No Communication made of delay or reschedule. No form 42 update made.

Corrective Action: Update Plugging operations with FORM 42 and email to inspector Mike Longworth Date: 01/10/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402920792	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5627775">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5627775</a>
701102489	Inspection 701102488 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5627774">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5627774</a>