

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2022

Submitted Date:

02/01/2022

Document Number:

690202540

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 COSTA, RYAN 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 16830

Name of Operator: CHOLLA PRODUCTION LLC

Address: 10390 BRADFORD RD #201

City: LITTLETON State: CO Zip: 80127

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

8 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|-------|---------------------------|---------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Kosola, Jason | | jason.kosola@state.co.us | |
| HUNDLEY-GOFF EMILY | | cholla_production@msn.com | |
| LEVENGOD JOHN | | jlevengood07@gmail.com | |
| LEVENGOD SARAH | | doveratwoodcorp@yahoo.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------------------|--------|-------------|------------|---------|---------------------------------------|-------------|
| 438617 | GAS COMPRESSOR STATION | AC | 08/19/2014 | | - | S. Bear Creek Compressor & Treater | RI |

General Comment:

This is a location inspection.
 See attached photos and additional details within this report.

Operator of record shows CHOLLA PRODUCTION LLC however sign at the location is shown to be DOVER ATWOOD CORPORATION.
 No form 10 was found in the well file. Both Operators have been included to this inspection.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|------------|
| Type | BATTERY | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 03/02/2022 |

Emergency Contact Number:

| | | | |
|--------------------|---|-------|------------|
| Comment: | The emergency contact number was not valid. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 02/02/2022 |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | STORAGE OF SUPL | | |
| Comment: | There is various unused supplies pipe, fittings, stored on location. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 02/16/2022 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | There is an unused compressor stored on location. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 03/02/2022 |

Overall Good: ☐**Spills:**

| | | | | |
|--------------------|---|--------|--|------------------|
| Type | Area | Volume | | |
| Produced Water | Tank | | | |
| Comment: | There are signs that the open top tanks have leaked due to white stained soils. | | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. | | | Date: 03/02/2022 |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|--------------------|--|----------|----------------|---------|--------|------------|
| PRODUCED WATER | 1 | 100 BBLS | FIBERGLASS AST | | , | |
| Comment: | The tank at the east side of the location is filled nearly to the top with liquids and needs to be lowered to prevent from spilling over. Operator was notified by phone call of this issue. | | | | | |
| Corrective Action: | Comply with 912.d. Spill and Release Prevention. | | | | Date: | 02/02/2022 |

Paint

| | | | | |
|------------------|--|--|--|--|
| Condition | | | | |
| Other (Content) | | | | |
| Other (Capacity) | | | | |
| Other (Type) | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|------|----------|---------------------|---------------------|-------------|

| | | | | | |
|--------------------|---|--|----------------|---------|--------|
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| | 2 | 100 BBLs | FIBERGLASS AST | | , |
| Comment: | | Netting on open top tanks inadequate | | | |
| Corrective Action: | | Install or repair wildlife protection equipment. | | | |
| | | Date: 02/07/2022 | | | |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| | | | | |
|--------------------|------------|---------------------|---------------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | Inadequate | | | |
| Comment: | | | | There is no secondary containment installed at the open top tanks. |
| Corrective Action: | | | | Repair or install berms or other secondary containment devices per Rule 603.o. |
| | | | | Date: 03/02/2022 |

Venting:

| | | | |
|--------------------|-------|--|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | Date: | | |

Flaring:

| | | | |
|--------------------|-------|--|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | Date: | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 690202541 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5651755 |