

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/10/2022

Submitted Date:

02/11/2022

Document Number:

690900193**FIELD INSPECTION FORM**Loc ID 449274 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10706Name of Operator: D90 ENERGY LLCAddress: 952 ECHO LANE SUITE 480City: HOUSTON State: TX Zip: 77024**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Waldron, Emily		emily.waldron@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Boyer, David	303-994-0000	david@d90energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449275	WELL	PR	10/01/2020	OW	057-06598	REU 0681 1-23H2	EI

**General Comment:**

On February 10, 2022, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of D90 Energy LLC's (D90) Rabbit Ears 06851 23 Location (Location ID: 449274) and API 057-06598. Weather was partially cloudy and temperatures about 30 degrees Fahrenheit. Snow was covering the ground. For the most recent field inspection report of this facility, please refer to Document # 689806889.

The following is a summary:

The northern load valve spill container was full of ice (produced water [E&P waste]) and staining observed down the outside wall of the tank battery secondary containment and on the snow.

(3) 675 bbls produced water tanks.

(5) 675 bbls oil tanks

Tank battery drifted in with snow.

Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	Truck Loadout	<= 1 bbl		
Comment: The northern load valve spill container was full of ice (produced water [E&P waste]) and staining observed down the outside wall of the tank battery secondary containment and on the snow.				
Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.				Date: 03/11/2022

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLS	STEEL AST		,
Comment: (3) 675 bbls produced water tanks.					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:	Tank battery drifted in with snow.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	500 BBLS	STEEL AST		,
Comment:	(5) 675 bbls oil tanks.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<b><u>Berms</u></b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Tank battery drifted in with snow.					
Corrective Action:					Date:
<b><u>Venting:</u></b>					
Yes/No					
Comment:					
Corrective Action:				Date:	
<b><u>Flaring:</u></b>					
Type					
Comment:					
Corrective Action:				Date:	



**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: The northern load valve spill container was full of ice (produced water [E&P waste]) and staining observed down the outside wall of the tank battery secondary containment and on the snow.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 03/11/2022

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402955032	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5663052">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5663052</a>
690900194	INSP Photo Rabbit Ears Location 449274 20220210	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5663049">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5663049</a>