

Inspection Photos

Location Name: Terri 14-4

Location ID: 320096



Pic 1 Flowline valves, and master valve were in the open position at time of inspection. Valves were put in close position, and LOTO installed on master valve. All P3 wells are in need of annual bradenhead test.



Pic 2 both tanks appear to have fluid inside.

Inspection Photos
Location Name: Terri 14-4
Location ID: 320096

Mar 1, 2022 at 4:12:43 PM
39.985943,-104.558618
Adams County
COGCC



Pic 3 gas meter run

Mar 1, 2022 at 4:12:54 PM
39.985968,-104.558485
Adams County
COGCC



Pic 4 separator, ECD.