

Inspection Photos
Operator: Morningstar Operating
API: 007-06200
Date: 2/28/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation such as rubber rabbitbrush, sand dropseed, and western wheatgrass observed.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of erosional channeling observed near the well pad entrance, approx. 12 inches wide and deep.




Photo 5. View of diversion channel in the southeastern project area, approx 12-15in wide and deep. BMPs are needed for stabilization.



Photo 6. View of reference area comprised of pinyon and juniper woodland with sagebrush, blue grama, prickly pear, and snakeweed in the understory.