

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2022

Submitted Date:

03/04/2022

Document Number:

701004631**FIELD INSPECTION FORM**Loc ID 321034 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	BACA Inspections
Crane, Shaun	719-353-2526	cimbaca.production.services@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205836	WELL	PR	11/01/2021	GW	009-06251	FRAZEE 1	PR

General Comment:Routine Inspection

Location					
Lease Road:					
Type	Access				
comment:	Two track through pasture				
Corrective Action					Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Lease sign mounted to fence				
Corrective Action:					Date:
Type	TANK LABELS/PLACARDS				
Comment:	Sticker on tank. Needs capacity label				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: _____
Good Housekeeping:					
Type	DEBRIS				
Comment:	Pipe fence laying on the ground next to cathodic rectifier				
Corrective Action:	Remove unused fencing				Date: 04/03/2022
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:	<input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	OTHER				
Comment:	Pipe fence around cathodic rectifier				
Corrective Action:					Date:
Type	PUMP JACK				
Comment:	Wire panels around unit and wellhead				
Corrective Action:					Date:
Type	SEPARATOR				
Comment:	Wire fence around HGS				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.211400,-102.254020

Comment:	Fiberglass open top water tank. Tank needs removed from location or install berms		Date:	
Corrective Action:			Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)	150bbbs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	205836	Type:	WELL	API Number:	009-06251	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402973314	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5681572
701004644	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5681568