

Inspection Photos

API: 043-06196

Operator: JAVERNICK OIL

Inspection Date: 3/15/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06196 | Date: 3/15/2022

Inspection Photos



Photo 1. Drone aerial photo facing south along the access road. There is erosion along this area of the road which needs to be repaired and stabilized. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06196 | Date: 3/15/2022

Inspection Photos



Photo 2. Drone aerial photo facing west toward the location. Most of the location is revegetated. The open hole shown at red arrow still remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06196 | Date: 3/15/2022

Inspection Photos



Photo 3. Facing down toward the open hole where the well was cut and capped. The open hole is about 4.5 ft. deep. There is cement debris next to the hole which appears to be from plugging of the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06196 | Date: 3/15/2022

Inspection Photos



Photo 4. Facing south at the location. The cut slope is shown at red arrow which needs to be reclaimed. There are areas at the location that have not re-established vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06196 | Date: 3/15/2022