

TEP  
RWF 311-15  
Location # 335571



location



Location/ lack of stabilization-compaction

TEP  
RWF 311-15  
Location # 335571



**Location/ lack of stabilization-compaction**



**Location/ lack of stabilization-compaction**

TEP  
RWF 311-15  
Location # 335571



**Location/ lack of stabilization-compaction**



**Location/ lack of stabilization-compaction**

TEP  
RWF 311-15  
Location # 335571



Stored equipment/ random debris



Stored equipment

TEP  
RWF 311-15  
Location # 335571



**Location/ lack of stabilization-compaction**



**location/ lack of stabilization-compaction**

TEP  
RWF 311-15  
Location # 335571



Well head leaking



Well head leaking

TEP  
RWF 311-15  
Location # 335571



**Location/ lack of stabilization-compaction/ open hatches on tanks**



**location/ open piping and tank hatches**

TEP  
RWF 311-15  
Location # 335571



**Debris**



**Open ended piping**

TEP  
RWF 311-15  
Location # 335571



**Cut slope lack of stabilization**



**Cut slope lack of stabilization**

TEP  
RWF 311-15  
Location # 335571



**Cut slope lack of stabilization**



**Cut slope lack of stabilization**