

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/14/2022

Submitted Date:

03/16/2022

Document Number:

688801106

FIELD INSPECTION FORMLoc ID 326095 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215859	WELL	PR	05/30/1990	GW	067-07464	THOMAS JACQUEZ B 1	EI

General Comment:

On March 14, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Thomas Jacquez B #1. For the most recent field inspection report of this facility, please refer to document #693903711.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Free standing sign near location entrance.			
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	Lube oil containers are labeled and have placards.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Tanks have signs with contents, capacity, and NFPA placards.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Lube Oil	Separator	<= 1 bbl		
Comment:	Stained gravel near 5 gallon bucket outside of sound wall.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 04/15/2022
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:	Stock panel enclosure around one of the 21 bbl. produced water PBVs.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Sound walls around compressor.			
Corrective Action:				Date:
Equipment:				
Type: Deadman # & Marked	# 4			corrective date
Comment:	Only one marker observed during this inspection.			
Corrective Action:				Date:

Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.100736,-107.916595	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	21 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.100677,-107.916284	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	21 bbl.	
Other (Type)		

Berms

Inspector Name: Hughes, Jim

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

AirsID

API Number
067-07464

API Number	AirsID
------------	--------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215859	Type:	WELL	API Number:	067-07464	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	Lube oil containers on secondary containment.
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Chemical injection system on secondary containment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On March 14, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Thomas Jacquez B #1. For the most recent field inspection report of this facility, please refer to document #693903711. Only one rig anchor marker was observed during this inspection. A partially buried 5 gallon bucket outside of the sound walls has staining around it.	hughesjo	03/16/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402986879	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5695684
688801107	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5695683