

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2022

Submitted Date:

04/12/2022

Document Number:

688801148

FIELD INSPECTION FORMLoc ID 333532 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Killough, Mitch		mkillough@hilcorp.com	
		FarmingtonRegulatoryTechs@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262060	WELL	PR	08/20/2003	GW	067-08671	R&G 26-2	EI
424065	WELL	PR	12/02/2011	GW	067-09862	R&G 26-3	EI

General Comment:

On April 11, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Company R&G #26-2. For the most recent field inspection report of this facility, please refer to document #693904377.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Labels are peeling off of tanks.			
Corrective Action:	Install signs to comply with Rule 605.h.			Date: 05/12/2022
Type	WELLHEAD			
Comment:	Free standing signs near location entrance.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Perimeter fencing around well heads and pump jacks. Guard fencing present on both pump jacks.			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Pump Jack	# 2			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	Telemetry equipment.			
Corrective Action:				Date:
Type: Vertical Heated Separator	# 2			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:				Date:

Type: Ancillary equipment	# 2	
Comment:	Electrical supply equipment and electric pump controllers.	
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 2	
Comment:	Electric motors.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	HEATED STEEL AST		37.071837,-107.573679
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined metal secondary containment ring. Previous inspection noted standing water inside the secondary containment. The operator inspected the ASTs and reported that the accumulated water was storm water.			
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
067-08671
067-09862

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: <u>262060</u>	Type: <u>WELL</u>	API Number: <u>067-08671</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>424065</u>	Type: <u>WELL</u>	API Number: <u>067-09862</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
	hughesjo	04/12/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403013474	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5722033
688801149	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5722032