



**Inspected Facilities**

Facility ID: 299576 Type: WELL API Number: 123-29426 Status: SI Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment:	COGCC Environmental Inspection of well decommissioning, Remediation Project 21172. Well excavation has been backfilled. Operator to submit results of soil sampling and laboratory analysis on Form 27 Supplemental.	
Corrective Action:	Submit results of soil sampling and laboratory analysis on Form 27 Supplemental by June 30, 2022.	Date: <u>06/30/2022</u>

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403013247	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721825">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721825</a>
693700935	Mesbergen 45-3D well location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721808">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721808</a>