

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2022

Submitted Date:

04/12/2022

Document Number:

700600372

**FIELD INSPECTION FORM**

Loc ID 308186 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263951	WELL	PR	07/27/2003	GW	071-07643	GRAHAM 22-22	EI
423586	WELL	PR	09/17/2011	GW	071-09874	GRAHAM 32-22 TR	EI

**General Comment:**

This inspection is in response to COGCC Complaint 403006808 which reported a spill on the Graham location.

COGCC Environmental inspection found evidence of a spill of an unknown volume from Graham 22-22 well. Soil around pumpjack has salt impacts. See attached photos.

The Graham 32-22 TR also shows signs of a slow leak with the wellhead covered in dried salts.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Both wells on location have signs of recent slow leak from wellhead. Salt impacts are evident around the Graham 22-22 well. Salt has coated the Graham 32-22 TR wellhead.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	04/13/2022

Overall Good:

**Spills:**

Type	Area	Volume	
Produced Water	WELLHEAD		
Comment:	Produced water spill from wellhead has left a salt impacted area around the wellhead. See attached photos.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Remove impacted soil from location to prevent transport of impacts of location.	Date:	05/12/2022

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 263951 Type: WELL API Number: 071-07643 Status: PR Insp. Status: EI

Facility ID: 423586 Type: WELL API Number: 071-09874 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 270504      Lat: 37.245651      Long: -104.769267

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: Other      Liner Condition: Adequate

Comment: Pit size is drastically different than permitted size. Aerial photo records show that pit size has been reduced from original constructed size.

Corrective Action

Operator shall submit Form 15 to update the pit facility record. Operator shall review pit facility records and correct any incorrect information.

Date: 05/12/2022

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403012431	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5720912">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5720912</a>
700600373	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5720911">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5720911</a>