

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2022

Submitted Date:

04/12/2022

Document Number:

700704075

FIELD INSPECTION FORM

 Loc ID 334783 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

3 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89066	WELL	PR	05/15/2000	GW	045-07396	COUEY 17-14 (N17E)	PR
89071	WELL	PR	05/15/2000	GW	045-07401	COUEY 17-15 (N17E)	PR
264178	WELL	PR	05/20/2005	GW	045-08189	COUEY 17-12A (N17E))	PR

General Comment:[COGCC Inspection Report Summary](#)

On Monday 4/12/2022 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus N17E, at Location # 334783 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Access and location shows some signs in areas of lack of stabilization/ compaction/ degradation/ erosion.
2. Lack of battery signage.
3. Two lines are not marked.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	See stormwater		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage		Date: <u>07/01/2022</u>
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Two lines are not marked. See Photos.		
Corrective Action:	Mark risers		Date: <u>05/06/2022</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	1 chemical tank in plastic containment and 1 500 gallon methanol tank in metal containment		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 89066 Type: WELL API Number: 045-07396 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 89071 Type: WELL API Number: 045-07401 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 264178 Type: WELL API Number: 045-08189 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
		Compaction	Fail			

Comment: [1. Access and location shows some signs in areas of lack of stabilization/ compaction/ degradation/ erosion.](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 06/03/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403012670	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721090
700704081	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721081