

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2022

Submitted Date:

04/12/2022

Document Number:

702000155

**FIELD INSPECTION FORM**Loc ID 312863 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                            | Comment |
|--------------|-------|----------------------------------|---------|
|              |       | dnr_cogccengineering@state.co.us |         |
| Evans, Clay  |       | antlerenergy@yahoo.com           |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 222661      | WELL | PR     | 06/01/2015  | GW         | 081-06021 | FEDERAL-CHAMBERLIN 22-1 | PR          |

**General Comment:**

Routine follow up inspection. Follow up to inspection from 1/3/2022 document number 689806873 and 11/16/2020 document number 689804992. No corrective actions appear to have been made. Compliance issues remaining:

heated vertical separator is less than 50 feet from heated crude oil tanks

Compliance issues observed during this inspection:

stained soil at wellhead

chemical barrels blown over and have become debris

tubing stored at wellhead

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | OTHER  |       |            |
| Comment:           | Stained soil at wellhead.  |       |            |
| Corrective Action: | Comply with Rule 606<br>Properly dispose of oily waste in accordance with 905.e. | Date: | 05/12/2022 |
| Type               | STORAGE OF SUPL  |       |            |
| Comment:           | Tubing stored at wellhead.   |       |            |
| Corrective Action: | Comply with Rule 606   | Date: | 05/12/2022 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                                 |  |  |                  |
|---------------------------------|--|--|------------------|
| <b>Equipment:</b>               |  |  | corrective date  |
| Type: Vertical Heated Separator | # 1  |  |                  |
| Comment:                        | Less than 50 feet from heated crude oil tanks. 40.90355, -108.28435        |  |                  |
| Corrective Action:              | Move equipment to comply with minimum 75 foot setback as per Rule 608.a.5. |  | Date: 02/27/2015 |
| Type: Bird Protectors           | #  |  |                  |
| Comment:                        |  |  |                  |
| Corrective Action:              |  |  | Date:            |
| Type: Bradenhead                | # 1  |  |                  |
| Comment:                        |  |  |                  |
| Corrective Action:              |  |  | Date:            |

|                    |     |       |
|--------------------|-----|-------|
| Type: Pump Jack    | # 1 |       |
| Comment:           |     |       |
| Corrective Action: |     | Date: |

**Tanks and Berms:**

|                    |   |          |                  |         |        |
|--------------------|---|----------|------------------|---------|--------|
| Contents           | # | Capacity | Type             | Tank ID | SE GPS |
| CRUDE OIL          | 2 | 400 BBLS | HEATED STEEL AST |         | ,      |
| Comment:           |   |          |                  |         |        |
| Corrective Action: |   |          |                  |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities |   |       |      |             |           |         |    |               |            |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|------------|
| Facility ID:         | 222661  | Type: | WELL | API Number: | 081-06021 | Status: | PR | Insp. Status: | PR         |
| Producing Well       |   |       |      |             |           |         |    |               |            |
| Comment:             | Produced volumes are required to be reported accurately from the wellhead meter every month, and the form 7 reporting does not reflect that accurate measurement. |       |      |             |           |         |    |               |            |
| Corrective Action:   | Submit required Form 7(s) to COGCC per rule 413.  |       |      |             |           |         |    | Date:         | 05/12/2022 |

|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|
|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403012887    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721487">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721487</a> |
| 702000160    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721479">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721479</a> |