

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/13/2022

Submitted Date:

04/21/2022

Document Number:

688000639

**FIELD INSPECTION FORM**

Loc ID 330667 Inspector Name: YOUNG, ROB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
330667	LOCATION	AC			-	D.O.C. SHOWERS-68N60W 32NWSW	EI

**General Comment:**

Environmental inspection related to Rem #17544 and Rem #11274. Both projects require additional data to be provided to COGCC before they can be closed.

**Inspected Facilities**

Facility ID: 330667 Type: LOCATION API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: Additional boron data was to be supplied for Rem #17544 and Rem 11274 had a COA for assessment at the skim tank location and soil suitability parameters confirmed in the SS07 - SS10 area.

Corrective Action: Provide supplemental Form 27 updates with the requested information.

Date: 05/20/2022

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403023953	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5730763">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5730763</a>
688000640	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5730739">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5730739</a>