

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/19/2022

Submitted Date:

04/19/2022

Document Number:

699804396

**FIELD INSPECTION FORM**
 Loc ID 335039 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                     | Comment |
|--------------|-------|---|---------|
| , Caerus     |       | COGCC.inspections@caerus<br>oilandgas.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                 | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------|-------------|
| 298322      | WELL | PR     | 05/12/2009  | GW         | 045-17141 | SAVAGE 20-8 (PI20)            | PR          |
| 298323      | WELL | PR     | 05/07/2009  | GW         | 045-17140 | SAVAGE 20-8BB (PI20)          | PR          |
| 298324      | WELL | PR     | 05/12/2009  | GW         | 045-17139 | SAVAGE 20-9 (PI20)            | PR          |
| 298325      | WELL | PR     | 05/07/2009  | GW         | 045-17138 | SAVAGE FEDERAL 20-10BB (P120) | PR          |

**General Comment:****COGCC Inspection Report Summary**

On Monday 4/18/22 at approximately 12:30 hours, I, Inspector Corey De Paolo,  
Conducted a follow up inspection at CAERUS PICEANCE LLC SAVAGE-67S95W /20NESE.

Location #335039 in Garfield County Colorado.

Refer to document #699804119 inspection conducted on 2/7/22. Previous corrective actions have not been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) No battery sign located at the tank battery with a previous corrective action date of 4/7/22.
- 2) Water truck parked on location with a corrective action date of 4/26/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**Overall Good: ☒

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | WELLHEAD   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | OTHER  |       |            |
| Comment:             | Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank. |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | BATTERY  |       |            |
| Comment:             | No battery sign located at the tank battery.   |       |            |
| Corrective Action:   | A permanent, conspicuous sign will be located at the tank battery.   | Date: | 04/07/2022 |

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | STORAGE OF SUPL   |       |            |
| Comment:           | Water truck parked on location.   |       |            |
| Corrective Action: | The storage of equipment not necessary for use on location is prohibited. | Date: | 04/26/2022 |

Overall Good: ☐

|  |      |        |  |  |
|--|------|--------|--|--|
| <b>Spills:</b>   |      |        |  |  |
| Type   | Area | Volume |  |  |
| In Containment: No                                     |      |        |  |  |
| Comment: _____   |      |        |  |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |  |

|                    |                                   |       |  |
|--------------------|-----------------------------------|-------|--|
| <b>Fencing/:</b>   |                                   |       |  |
| Type               | LOCATION                          |       |  |
| Comment:           | Barbed wire fence around location |       |  |
| Corrective Action: |                                   | Date: |  |

|                       |                       |       |                 |
|-----------------------|-----------------------|-------|-----------------|
| <b>Equipment:</b>     |                       |       | corrective date |
| Type: Bird Protectors | # 1                   |       |                 |
| Comment:              |                       |       |                 |
| Corrective Action:    |                       | Date: |                 |
| Type: Plunger Lift    | # 4                   |       |                 |
| Comment:              | Wells on plunger lift |       |                 |

|                                 |                  |       |  |
|---------------------------------|------------------|-------|--|
| Corrective Action:              |                  | Date: |  |
| Type: Gas Meter Run             | # 4              |       |  |
| Comment:                        |                  |       |  |
| Corrective Action:              |                  | Date: |  |
| Type: Gas Meter Run             | # 1              |       |  |
| Comment:                        | Summit midstream |       |  |
| Corrective Action:              |                  | Date: |  |
| Type: Vertical Heated Separator | # 4              |       |  |
| Comment:                        |                  |       |  |
| Corrective Action:              |                  | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| CONDENSATE         | 3 | 300 BBLs | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          | Date:               |                     |             |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    |       |  |
|                    |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |           |       |      |             |           |         |    |               |    |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 298322    | Type: | WELL | API Number: | 045-17141 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | Producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298323    | Type: | WELL | API Number: | 045-17140 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | Producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298324    | Type: | WELL | API Number: | 045-17139 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | Producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 298325    | Type: | WELL | API Number: | 045-17138 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | Producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Sediment Traps          |                       |               |                          |         |
|                  |                 | Berms                   |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
| Ditches          |                 |                         |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
| Sediment Traps   |                 |                         |                       |               |                          |         |

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| Refer to Housekeeping and Signs/Markers for corrective actions. | depaoloc | 04/19/2022 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 403023086    | INSPECTION SUBMITTED        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729909">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729909</a> |
| 699804397    | Photos for Insp. #699804396 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729869">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729869</a> |