

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/19/2022

Submitted Date:

04/21/2022

Document Number:

696304129

FIELD INSPECTION FORMLoc ID 318901 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 49407

Name of Operator: KUGLER* DEAN & JOE DBA D-J OIL COMPANY

Address: P O BOX 72

City: NEW RAYMER State: CO Zip: 80742

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Binschus, Chris		chris.binschus@state.co.us	
Dean Kugler		dlkug@yahoo.com	
Wolfe, Stephen		stephen.wolfe@state.co.us	
Allison, Rick		rick.allison@state.co.us	
Joe Kugler		torchkugler@yahoo.com	
Kraich, Adam		adam.kraich@state.co.us	
,		dakugler@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242412	WELL	SI	11/01/2015	OW	123-10203	COLORADO FEDERAL 1	TA

General Comment:

Follow-Up Inspection to FIR 696303378 dated 06.22.2021

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Production Equipment STILL on Location Original Corrective Action Date still applies 11.25.2019 - Separator, Pumping Unit, Horse's Head, Wellhead parts and fittings, Engine, Engine Shed, 4 Deadman Anchors, Produced Water Tank, Crude oil Tanks, Flowlines. See photos		
Corrective Action:	Comply with Rule 606	Date:	11/25/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:		Shares berm with the Crude Oil Tanks			
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		40.630330,-103.851090	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 242412 Type: WELL API Number: 123-10203 Status: SI Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Well appears to have been Plugged and Abandoned around 07.08.2019, no Form 42 Notice of Plugging Operations was Submitted during that time. However on 06.15.2021 a Form 42 #402719350 for Start of Plugging 48-Hour Notice was Submitted with a Start Date of 06.15.2021 at 09:00

Approved Form 6 #2304069 dated 02.21.2019.
Form 6 Subsequential has been Submitted on 09.02.2021 per Form 6S - 402732234
STILL "IN PROCESS" NOT yet APPROVED
Well has been Cut and Capped.

No Equipment has been removed from this Location since the Well was Plugged and Abandoned in July of 2019
A Form 27 - For the Decommissioning of Oil and Gas Facilities was Submitted on 07.13.2021 per Doc ID 402738946
Location appears to be on Federal Surface

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 04/14/2022 at approximately 13:52, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Kugler* Dean and Joe DBD D-J Oil Company, Colorado Federal #1 at Location #318901 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Well appears to have been Plugged and Abandoned around 07.08.2019, no Form 42 Notice of Plugging Operations was Submitted during that time. However on 06.15.2021 a Form 42 #402719350 for Start of Plugging 48-Hour Notice was Submitted with a Start Date of 06.15.2021 at 09:00</p> <p>Approved Form 6 #2304069 dated 02.21.2019. Form 6 Subsequential has been Submitted on 09.02.2021 per Form 6S - 402732234 STILL "IN PROCESS" NOT yet APPROVED Well has been Cut and Capped.</p> <p>Location appears to be on Federal Surface. No Equipment has been removed from this Location since the Well was Plugged and Abandoned in July of 2019. A Form 27 - For the Decommissioning of Oil and Gas Facilities was Submitted on 07.13.2021 per Doc ID 402738946.</p> <p>Multiple Unused Equipment: Separator, Pumping Unit, Horse's Head, Wellhead parts and fittings, Engine, Engine Shed, Crude Oil Tanks (2), Produced Water Tanks. Comply with Rule 606. Corrective Action Date of 11/25/2019 REMAINS in Effect. Final Reclamation to begin 90 days after Plug and Abandonment.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection report.</p>	petrie	04/21/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403025781	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733549

696304130	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5733473
-----------	--------	---

