

Inspection Photos  
Operator: Enduring  
API: 067-07841  
Date: 5/13/2022



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Vegetation within the eastern project area remains dominated with annual weeds such as cheatgrass and jointed goatgrass. This needs to be assessed and managed until desirable perennial vegetation is established.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of perimeter silt fence that is no longer functioning and needs to be repaired or removed.



Photo 5. View of reference area pinyon and juniper woodland with understory of shrubs such as antelope bitterbrush, cliff fendlerbush, banana yucca, Indian ricegrass, and claret cup.