

Inspection Photos
Operator: Simcoe
API: 067-06546
Date: 5/27/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing within the project area with western wheatgrass, smooth brome, rubber rabbitbrush, and sand dropseed.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of cement block and electrical housing that do not appear to be in use.



Photo 5. View of reference area comprised of ponderosa pine woodland with gambel oak, antelope bitterbrush, sandberg bluegrass, black sage, and mules ears in the understory.