

Inspection Photos
Operator: Simcoe
API: 067-09503
Date: 5/27/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing within the project area with western wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of erosional channeling in the southern fill slope, approximately 1-2ft wide and deep.



Photo 5. View of reference area comprised of ponderosa pine woodland with gambel oak, antelope bitterbrush, sandberg bluegrass, black sage, and mules ears in the understory.