

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Crude Oil Tank missing Content Label; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 06/24/2022

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Wellhead. See photos		
Corrective Action:	Comply with Rule 606		Date: 06/24/2022
Type	STORAGE OF SUPL		
Comment:	Unused Equipment, supplies and parts on Entire Location. See Photos (Tanks, Separators, Pipes, Valves, Stairs, Tanks Catwalks)		
Corrective Action:	Comply with Rule 606		Date: 09/26/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire Fence		
Corrective Action:			Date:

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 1		
Comment:	Disconnected from Flowline		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.209670,-104.345370
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 260339 Type: WELL API Number: 123-20458 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 05/24/2022 at approximately 13:33, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at O'Brien Energy Resources Corp, Lost Creek 4-20, Location #331298 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Unused Equipment, Supplies and Parts on Entire Location. See Photos. Comply with Rule 606. Corrective Action Date 09.26.2022</p> <p>Crude Oil Tank missing Content Label. See Photos. Comply with Rule 605.h. Corrective Action Date 06.24.2022</p> <p>Unmarked Riser at Wellhead. See Photos. Comply with Rule 606. Corrective Action Date 06.24.2022</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report</p>	petrie	05/24/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403058279	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5762120
696304220	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5762117