

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

05/26/2022

Document Number:

700300411**FIELD INSPECTION FORM**Loc ID 333535 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.
,		regulatory@logosresourcesllc.com	All Inspections 8/2/2021

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214113	WELL	PR	01/29/1958	GW	067-05423	BONDAD 33-9 14	PR
474316	Domestic Tap	AC	03/26/2020		-	Domestic Tap 18SENW	AO

General Comment:

COGCC Compliance Supervisor Steve labowskie and Inspector Alex Klink conducted a joint inspection, See FIR doc# 702500056 for additional corrective actions.

Optical gas imaging inspection due to operator Form 7 reporting of gas flared. No gas flaring or venting observed. It appears gas used by equipment and domestic tap is being reported as gas flared.

Correctly report gas used and gas flared.

[See optical gas imaging report tab.](#)

Inspected FacilitiesFacility ID: 214113 Type: WELL API Number: 067-05423 Status: PR Insp. Status: PRFacility ID: 474316 Type: Domestic Tap API Number: - Status: AC Insp. Status: AO**Producing Well**

Comment: domestic gas taps must be registered and gas reported as "gas used" on monthly Form 7. Last several reports indicate "gas flared"

Corrective Action:

Date:

Optical Gas Imaging Survey

Survey Type: _____

Current Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: 2-5 (mph) Direction From: s Weather: Clear Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Water Tank(s)
				Separation Equipment
				Wellhead(s)

Comment: No venting or flaring of production gas observed. See end of report for link to uploaded FLIR footage of separator pneumatic function.

Corrective Action: Confirm continuous gas bleed on flange on back of separator is operating within manufacturers specs per Rule 608.e

Date: 06/28/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403061297	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5764685
700300414	FLIR footage separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5764683
700300415	domestic gas tap appears to associated to LOGOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5764684