

Inspection Photos
Location Name: M and M 6
Location ID: 325619



IMG 01
Well sign



IMG 02
Well sign





IMG 03
Site overview



IMG 04
Wellhead



IMG 05

Pump jack and prime mover



IMG 06

Tank with faded paint and no sign



IMG 07

Trailer is on edge of location



IMG 08

Equipment on edge of location



IMG 09

Burrows in secondary containment



IMG 10

Equipment on edge of location



IMG 11
Debris



IMG 12
Debris



IMG 13
Fence panel not in use



IMG 14
Oily residue has impacted material



IMG 15
Unmarked rig anchor