

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2022

Submitted Date:

06/01/2022

Document Number:

702500061

FIELD INSPECTION FORM

Loc ID 311925 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 10766
Name of Operator: ARKOMA OPERATIONS LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Contact Information:

Contact Name	Phone	Email	Comment
Price, Andrew	918-260-8324	aprice@arkomaops.com	All SW field inspections
, Engineering		dnr_cogccengineering@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269	WELL	PR	01/24/2018	GW	067-09491	IGE 138	PR
270210	WELL	PR	01/14/2005	GW	067-08895	HERRERA 1A	PR
270215	WELL	SI	03/01/2017	GW	067-08896	SEMLER 2	TA
295628	WELL	PR	02/13/2018	GW	067-09530	IGE 137	PR

General Comment:

Inspectors Alex Klink and Steve Labowskie on site to witness MIT. Inspector Alex Klink also conducted routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

The separator for the well Semler 2 has been removed. There are multiple unused flowlines associated with this well. This well appears temporarily abandoned. There is no Form 4 on record for Temporarily Abandoned.

Location			
Lease Road:			
Type	Access		
comment:	Gravel access road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:	Emergency contact present on well sign: 800-452-1578 and 911. No 24 hour operator number listed.		
Corrective Action:			Date:
Good Housekeeping:			
Type	OTHER		
Comment:	Oily residue is dripping from IGE 137 pump jack and has begun impacting material (IMG 11).		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	IGE 137 pump jack enclosed on three sides by chain link fence.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 4		corrective date
Comment:	Bradenheads are accessible		
Corrective Action:			Date:
Type: Flow Line	# 14		
Comment:	In use flow lines: 3 2" lines from wellheads to separator, 3 2" lines from separator to produced water tank, 3 2" lines from separator to meter house, 3 2" lines from meter house to pig station, 2 1" lines from wellheads to gas powered prime mover.		
Corrective Action:			Date:
Type: Flow Line	# 9		
Comment:	Not in use flow lines: 1 2" line from Semler 2 wellhead to separator, 1 3" and 1 1" flow line stubbed up near Semler 2 wellhead, 1 3", 2 2", and 1 1" flow line stubbed up near Semler 2 former separator location, 1 1" flow line stubbed up near northern meter house, 1 1" flow line stubbed up near plunger lift pump. In addition 1 2" poly flow line stubbing up near Semler 2 meter house is open ended (IMG 19).		
Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)		Date: 06/02/2022
Type: Gas Meter Run	# 4		

Comment:			
Corrective Action:			Date:
Type: Pig Station	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:	Vertical Separators vent stacks are screened properly		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		37.108847,-107.717631
Comment:	Above ground produced water tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	Produced Water	
Other (Capacity)	300 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Earth berm around produced water tank. Tank also has additional metal berm around base.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 269 Type: WELL API Number: 067-09491 Status: PR Insp. Status: PR

Facility ID: 270210 Type: WELL API Number: 067-08895 Status: PR Insp. Status: PR

Facility ID: 270215 Type: WELL API Number: 067-08896 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: The data from the MIT is as follows: Bridge plug present at 2950'. Perforated interval is 3016'-3058'. Tubing depth is 2920'. Casing pressure before test: 0 PSI, Tubing pressure before test: 0 PSI. Casing pressure at start of test: 399.7 PSI, Casing pressure 5 minutes: 399.4 PSI, Casing pressure 10 minutes: 399.3 PSI, Casing pressure final: 399.3 PSI. Refer to Image 25 for photo of completed field test.

Corrective Action: Submit Form 7 to correctly reprot well status as Temporarily Abandoned per rule 434.b.
 Submit Form 4 Sundry Notice as directed per rule 434.b. Date: 07/02/2022

Facility ID: 295628 Type: WELL API Number: 067-09530 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosion on northwest end of locatoin is encroaching on well pad (IMG 06).

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/16/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403065106	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768238
702500067	Photo Doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768235