

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2022

Submitted Date:

06/01/2022

Document Number:

702500063

FIELD INSPECTION FORM

Loc ID 326435 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		regulatory@logosresourcesllc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	All SW field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216488	WELL	PR	05/01/2020	GW	067-08094	IGNACIO 33-8 027	PR

General Comment:

Inspectors Alex Klink and Steve Labowskie on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

This inspection does not address CA's on access road from previous reclamation inspection.

Location			
Lease Road:			
	Type Access		
	comment: Gravel access road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
	Comment: Emergency contact listed on well sign: 1-866-598-6220 and 911. No 24 hour operator contact.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment: <input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type OTHER		
	Comment: Scale corrosion inhibitor container is enclosed by metal fence.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Bird Protectors	# 2		
	Comment: Vertical separator vent stacks are screened properly.		
Corrective Action:			Date:
Type: Other	# 1		
	Comment: Scale corrosion inhibitor container. Label is deteriorated and NFPA info not legible (IMG 13).		
Corrective Action:	Install label to comply with rule 605.h		Date: <u>07/01/2022</u>
Type: Vertical Heated Separator	# 2		
	Comment:		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
	Comment:		
Corrective Action:			Date:
Type: Flow Line	# 7		
	Comment: 2 2" lines from wellhead to separator, 2 2" lines leaving separators to meter run, 2 2" lines leaving meter house. 1 2" line leaving south separator to produced water tank.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
	Comment: Telemetry, cathodic protection		
Corrective Action:			Date:

Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.121426,-107.708231
Comment:	Partially buried produced water container with steel mesh top.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	Produced water	
Other (Capacity)	125 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Metal secondary containment around produced water tank.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 216488 Type: WELL API Number: 067-08094 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Rip Rap	Pass					
Waddles	Pass					

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.
Impacts of stormwater on southern end of location have been addressed and a Corrective Action has ben given to that operator.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

