

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2022

Submitted Date:

06/08/2022

Document Number:

699603242

**FIELD INSPECTION FORM**

Loc ID 427237 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427215	WELL	PR	02/01/2022	OW	123-34901	KOHLHOFF AC 09-65HN	PR

**General Comment:**

This is a WELL / BATTERY inspection.  
Well(s): 1: Producing | PR.  
Battery: Active.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Motor oil, Coolant.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Iron mesh panel.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by metal berms.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas engine drives pump jack. Surrounded by protective shed.		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	At wellsite: 1: Motor oil drum w/ drip containment. Placards. 1: Coolant drum w/ drip containment. Placards.  At Battery site: 1: ECD scrubber.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Gas Sales. Calibration card(s) indicates calibration within last year. Last calibration: 03/29/2022. Active, w/ production.  Gas Buy Back. Calibration card(s) indicates calibration within last year. Last calibration: 03/29/2022. Active.		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Crude storage vapor line combustor(s). Controls crude oil tanks vapors. Pilots: ON.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	

Other (Capacity) 60 Bbls.	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Shares berms w/ crude oil tanks &amp; produced H2O tanks.</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	FIBERGLASS AST		
Comment: <a href="#">Equalizer line connects produced H2O tanks. Insulated.</a>					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Shares berms w/ crude oil tanks &amp; produced H2O vault.</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLs	STEEL AST		40.589590,-104.452930
Comment: <a href="#">Equalizer lines connect 2 of 3 crude oil tanks.</a>					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Shares berms w/ produced H2O tank, vault.</a>				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 427215 Type: WELL API Number: 123-34901 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/05/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Date of last Brhd test > 1yr.  
Required reports not filed. Submit current Brhd test.  
Submit reports per Rule 207.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 06/06/2022 at approximately 17:49 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: KOHLHOFF AC /09-65HN                      Location ID: 427237                      Well Name(s): Kohlhoff AC 09-65HN.                      API: 05-123-34901.                      Location County: Weld County, Colorado                      Weather: Mostly Cloudy, damp from storm.</p> <p>While there, I observed:                      Well(s): 1: Producing   PR.                      Battery: Active.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/08/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699603243	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773439">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773439</a>