

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2022

Submitted Date:

06/03/2022

Document Number:

702500068**FIELD INSPECTION FORM**Loc ID 306933 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 7125Name of Operator: BEEMAN OIL & GAS LLCAddress: 3401 QUEBEC ST SUITE 9105City: DENVER State: CO Zip: 80207**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stepp, Sarah		wcciassistant@gmail.com	<a href="#">All SW field inspections</a>
Galloway, Kelly		kgallowaywerc@gmail.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280138	WELL	PR	08/01/2020	OW	067-09070	HUBBS 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt access road		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type			
Comment:	Well sign displays inaccurate API		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	07/02/2022

Emergency Contact Number:			
Comment:	Emergency contact: 970-210-2896 and 911		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Pump jack enclosed by steel pipe fencing. Combustor enclosed by metal fence.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 2		
Comment:	2" line from wellhead to combustor, 2" line from wellhead to off site.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Combustor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric prime mover		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:	Combuster hooked up to casing head, not combusting or venting at time of inspection, no current approved Sundry to vent/flare, no gas capture plan of Rule 903 variance in process.		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403067903	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770523">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770523</a>
702500074	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770514">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770514</a>