

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2022

Submitted Date:

06/03/2022

Document Number:

702500070**FIELD INSPECTION FORM**Loc ID 325619 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Williford, Hearne		hwilli@swbell.net	All SW field inspections
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215114	WELL	PR	02/01/2020	OW	067-06719	M & M 6	PR

**General Comment:**

Inspectors Alex Klink and Steve Labowskie on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Dirt access road		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Well sign is posted behind fence panel and not legible.		
Corrective Action:	Install sign to comply with rule 605.g		Date: 07/02/2022
Type	TANK LABELS/PLACARDS		
Comment:	Crude Oil tank placard is deteriorated.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 07/02/2022
Emergency Contact Number:			
Comment:	Emergency numbers listed: 918-712-8828 and 911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Fence panel is not in use (IMG 13).		
Corrective Action:	Use or remove unused equipment per rule 606.		Date: 06/17/2022
Type	DEBRIS		
Comment:	Thread protectors (IMG 11) and steel cable (IMG 12) present on location.		
Corrective Action:	Remove debris to comply with rule 606.		Date: 06/17/2022
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Pump jack is enclosed on 3 sides by steel pipe fencing.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Deadman # & Marked	# 4	corrective date	
Comment:	4 rig anchors, one rig anchor is unmarked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 06/16/2022
Type: Flow Line	# 1		
Comment:	2" line from wellhead to tank battery.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		37.138011,-108.103060	
Comment:	Crude oil tank paint has deteriorated (IMG 06).					
Corrective Action:	Paint tank per rule 425.				Date:	09/02/2022

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Maintenance required due to animal burrows (IMG 09).			
Corrective Action:	Repair berms or other secondary containment devices. Since this facility does not require major modification it falls under the old Rule 605a.(4)			Date: 07/02/2022

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403067905	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770525">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770525</a>
702500072	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770516">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770516</a>