

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2022

Submitted Date:

06/14/2022

Document Number:

699804597

**FIELD INSPECTION FORM**Loc ID 334807 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210764	WELL	PR	09/17/1993	GW	045-06522	FEDERAL MV-12-3	PR
272043	WELL	PR	08/25/2004	GW	045-10007	FEDERAL GM 412-3	PR
272044	WELL	PR	08/22/2004	GW	045-10006	FEDERAL GM 312-3	PR
272045	WELL	PR	08/23/2004	GW	045-10005	FEDERAL GM 512-3	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 6/13/22 at approximately 13:30 hours, I, Inspector Corey De Paolo,  
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3SWNW.  
Location #334807 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) Multiple Loadline open ended with a corrective action date of 6/20/22.
- 2) Vent pipes on tank open ended with a corrective action date of 6/20/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Loadline open ended.		
Corrective Action:	All loadlines will be bullplugged or capped.	Date:	06/20/2022

Type: Bradenhead	# 4	
Comment:	Pressure transducers located on braden head. All braden head valves are accessible	
Corrective Action:		Date:
Type: Gas Meter Run	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 4	
Comment:	All wells on plunger lift	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Other	# 2	
Comment:	Vent pipes on tank open ended.	
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.	Date: 06/20/2022

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	210764	Type:	WELL	API Number:	045-06522	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	272043	Type:	WELL	API Number:	045-10007	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	272044	Type:	WELL	API Number:	045-10006	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	272045	Type:	WELL	API Number:	045-10005	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Berms						
Sediment Traps						
		Check Dams				
		Sediment Traps				
		Culverts				
Ditches						
		Berms				
Compaction						
		Ditches				
		Gravel				
		Hydro Mulch				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Refer to Equipment for corrective actions.	depaoloc	06/14/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403078351	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5778825">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5778825</a>
699804598	Photos for Insp. #699804597	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5778819">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5778819</a>