

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2022

Submitted Date:

06/17/2022

Document Number:

700600392**FIELD INSPECTION FORM**Loc ID 309609 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 61250Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beilman, James	316-734-8108	JBeilman@mulldrilling.com	Environmental/Safety Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267113	WELL	SI	04/01/2018	ERIW	073-06304	Meteor Unit 2	EI
432414	TANK BATTERY	AC	04/04/2013		-	VICK A	EI
482362	SPILL OR RELEASE	AC	06/15/2022		-	Meteor Unit #2; fka Vick A #1-9	EI

General Comment:[This is an environmental inspection to document spill 482362.](#)[Form 19 Initial Spill Report has already been submitted.](#)[Operator shall ensure that impacted area inside tank battery containment is compliant with Table 915-1 before returning to service.](#)

Inspected FacilitiesFacility ID: 267113 Type: WELL API Number: 073-06304 Status: SI Insp. Status: EIFacility ID: 432414 Type: TANK API Number: - Status: AC Insp. Status: EIFacility ID: 482362 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Spill of crude oil and produced water into containment as a result of fire.

Corrective Action: Form 19 spill report has already been submitted. Date: _____

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403082742	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782666
700600393	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782665