

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/16/2022

Submitted Date:

06/17/2022

Document Number:

700704325

**FIELD INSPECTION FORM**

Loc ID 335540	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 16 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289262	WELL	PR	01/01/2022	GW	045-13707	BURCKLE A1	PR
289263	WELL	PR	07/07/2011	GW	045-13706	Burckle Federal A2	PR
289264	WELL	PR	01/01/2022	GW	045-13705	BURCKLE A3	PR
289997	WELL	PR	01/01/2022	GW	045-13960	BURCKLE A7	PR
289998	WELL	SU	12/13/2012	GW	045-13959	Burckle A8	SU
291710	WELL	PR	01/01/2022	GW	045-14516	BURCKLE A11	PR
291712	WELL	PR	01/01/2022	GW	045-14515	BURCKLE A9	PR
297862	WELL	SU	10/07/2019	LO	045-16989	Burckle A5	SU
297863	WELL	SI	12/20/2012	GW	045-16990	Burckle A6	ND
298250	WELL	PR	07/02/2011	GW	045-17096	BURCKLE FED CA A10	PR
298251	WELL	PR	08/15/2011	GW	045-17097	BURCKLE FED CA A12	PR
422091	WELL	PR	07/08/2011	GW	045-20490	Burckle Federal A14	PR
422095	WELL	PR	08/15/2011	GW	045-20491	Burckle Federal A13	PR

**General Comment:**

COGCC Inspection Report Summary

On Thursday 6/16/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Burkle A, at Location # 335540 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following possible compliance issues were observed:

1. Some erosion on cut slopes sediment is running under and over waddles.
2. Subsidence at well heads.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	200 BBLS	STEEL AST		,	
Comment:	1 tank is heated					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	300 BBLS	STEEL AST		,	
Comment:	1 tank is heated					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities									
Facility ID:	289262	Type:	WELL	API Number:	045-13707	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	289263	Type:	WELL	API Number:	045-13706	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	289264	Type:	WELL	API Number:	045-13705	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	289997	Type:	WELL	API Number:	045-13960	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	289998	Type:	WELL	API Number:	045-13959	Status:	SU	Insp. Status:	SU
Facility ID:	291710	Type:	WELL	API Number:	045-14516	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291712	Type:	WELL	API Number:	045-14515	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	297862	Type:	WELL	API Number:	045-16989	Status:	SU	Insp. Status:	SU
Facility ID:	297863	Type:	WELL	API Number:	045-16990	Status:	SI	Insp. Status:	ND
Facility ID:	298250	Type:	WELL	API Number:	045-17096	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID: 298251    Type: WELL    API Number: 045-17097    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID: 422091    Type: WELL    API Number: 045-20490    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID: 422095    Type: WELL    API Number: 045-20491    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					
Drains						

Comment: 1. Some erosion on cut slopes sediment is running under and over waddles.(C/A date remains the same as previous inspection)  
2. Subsidence at well heads.(C/A date for subsidence at well heads is 7/29/2022)

Corrective Action: **Install or repair required BMPs**

Date: 03/13/2022

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403083119	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782996">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782996</a>
700704335	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782991">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782991</a>