

# Inspection Photos and Issue Report

7/11/2022

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334183

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 1:** Photos 1-2 taken from the northwest end of the Location. Photos provide an overview of the working pad from east, southeast south to southwest

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



July 11, 2022



July 11, 2022

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 3:** Wells on the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



July 11, 2022



July 11, 2022

**Photo 4:** Photo left taken from the southeast end of the Location, facing east. Photo right taken from the northwest end of the Location, facing west. Photos provide an overview of the Interim areas of the Location; interim areas are predominantly an annual cheat grass monoculture with pockets of perennial wheatgrass species

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 5:** Photo shows starting point of the “Disturbance 1” (D1) transect on the southern interim areas of the Location, facing east.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



July 11, 2022



July 11, 2022

**Photo 6:** Photos show the interim areas of the location at the 50<sup>th</sup> point of the D1 transect, facing north and south.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 7:** Interim areas surface at the 50<sup>th</sup> point of the D1 transect.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 8:** Photo shows the end point of the “Disturbance 1” (D1) transect on the southern interim areas of the Location, facing west.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 9:** Photo shows starting point of the “Disturbance 2” (D2) transect on the northwestern interim areas of the Location, facing southwest

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 10:** Photos show the interim areas of the location at the 50<sup>th</sup> point of the D2 transect, facing southeast and northwest.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 11:** Interim areas surface at the 50<sup>th</sup> point of the D2 transect

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 12:** Photo shows end point of the “Disturbance 2” (D2) transect on the northwestern interim areas of the Location, facing northeast.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 13:** Photo shows starting point of the “Reference Area” transect east of the Location, facing east.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 14:** Photos shows at the 50<sup>th</sup> point of the Reference Area transect, facing North and South.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 15:** Surface at the 50<sup>th</sup> point of the Reference Area transect

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334183



**Photo 16:** Photo shows the end point of the “Reference Area” transect north of the Location, facing west.