

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2022

Submitted Date:

07/22/2022

Document Number:

702500266**FIELD INSPECTION FORM**Loc ID 326349 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216284	WELL	PR	02/01/2011	CBM	067-07890	LAMKE A 1	PR
412450	WELL	PR	06/07/2021	GW	067-09761	LAMKE A 3	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Lube oil on A3 wellhead has impacted surface material (IMG 03 and 04).		
Corrective Action:	Remove oily residue and impacted material and dispose of in approved manner per rule 906 and 1002.f.		Date: 07/29/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Equipment on location enclosed by stock panel.		
Corrective Action:			Date:

Equipment:

Type: Vertical Heated Separator	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Gas meter calibrations are up to date.		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Telemetry, electric cabinet, 2 pump control panels		
Corrective Action:			Date:
Type: Flow Line	# 8		
Comment:	3 4" lines from wellheads to separators, 3 4" lines and 2 3/4" lines stubbed up near A1 wellhead		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	Linear rod pumps		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:			Date:
Type: Prime Mover	# 2		

Comment:	electric		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.166644,-107.707572	
Comment:	Double walled paritally buried produced water tank.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)	double walled	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Double walled tank.				
Corrective Action:					Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 216284 Type: WELL API Number: 067-07890 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 412450 Type: WELL API Number: 067-09761 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
		Gravel	Pass			
Compaction	Pass					
Ditches	Pass					
		Compaction	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500267	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810079