

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/18/2022

Submitted Date:

07/19/2022

Document Number:

702500244**FIELD INSPECTION FORM**
 Loc ID 312037 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
363	WELL	PR	02/01/2011	CBM	067-09495	SCHUYLER 34-9 30-2A	PR
216505	WELL	PR	05/01/1998	CBM	067-08111	SCHUYLER 34-9 30-2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank sign is deteriorated and not legible (IMG 05).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/18/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Lube oil at both wellheads has impacted material (IMG 03 and IMG 04).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.	Date:	07/28/2022
Type	OTHER		
Comment:	Fitting in compressor house is releasing produced water. Released produced water is contained within compressor house, but requires immediate attention to prevent produced water from impacting surface material.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	07/19/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Produced water tank is enclosed by wire fencing.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Gas meter calibrations are within the last year.		
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	Electric		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:		Date:	
Type: Flow Line	# 11		
Comment:	2 3" a 2" and 2 1" lines from wellhead to separator, 2 3" a 2" and 2 1" lines from wellhead to separator, line from separators to produced water tank		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Telemetry, pump control panel, electric panel.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Compressor in house within produced water secondary containment.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		STEEL AST		37.158363,-107.864783
Comment:	Above ground produced water tank.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Gravel and dirt earth berms.			
Corrective Action:			Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 363 Type: WELL API Number: 067-09495 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 216505 Type: WELL API Number: 067-08111 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass					
		Compaction	Pass			
Waddles	Pass					
Gravel	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403109431	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5806771
702500245	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5806766