

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2022

Submitted Date:

07/21/2022

Document Number:

693701018**FIELD INSPECTION FORM**Loc ID 323125 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Remediation-Spill, PDC		COGCCSpillRemediation@pdce.com	
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	All PDC inspection
Kosola, Jason		jason.kosola@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482570	SPILL OR RELEASE	AC	07/18/2022		-	Wacker Sec. 10	EI

**General Comment:**



**Environmental****Spill/Remediation:**

Comment: COGCC inspection of Spill ID 482570 reported by Operator "Off-location mist, 1-2 gallons estimated total with a miniscule amount going off location. " Opertaor provided incorrect lat/lon on Form 19 Initial Report. Based on field visit and discussion with onsite PDC personnel, Spill originated from compressor located at the Wacker 10G-302 well.

No standing liquid or impacted material was observed. Road base around the Wacker 10G-302, 10G-212 and 10G-312 has been replaced.

Corrective Action:

Operator shall provide correct lat/lon Form 19 Supplemental Report.

Date: 10/12/2022

Operator shall ensure and document on Form 19 Supplemental that confirmation soil samples are collected from beneath the replaced road base.

Due date is for supplying correct lat/lon and soil samples by the required 90 day Spill closure date.

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403112633	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809488">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809488</a>
693701019	Edge of replaced road base Wacker 10G-312	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809482">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809482</a>
693701020	Looking east from Wacker 10G-302	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809483">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809483</a>
693701021	Wacker 10G-302 and compressor	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809484">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809484</a>
693701022	Wacker 10G-302 and compressor	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809485">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5809485</a>