

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2022

Submitted Date:

07/20/2022

Document Number:

691201636

FIELD INSPECTION FORM

 Loc ID 335736 Inspector Name: Graber, Candice (Nikki) On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Information:

Contact Name	Phone	Email	Comment
Levi Kirk		lkirk@marcomllc.net	
Kevin Tautkus		ktautkus@marcomllc.net	KPK Primary Contractor
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Canfield, Chris		chris.canfield@state.co.us	
Gorka, Ray		RGorka@kpk.com	KPK environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272093	WELL	SI	04/01/2022	OW	001-09503	SACK 7-11	EI

General Comment:

COGCC environmental inspection to witness confirmation sampling at the Sack 8-11 wellhead. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

Third party contractors were conducting screening and sampling of wellhead excavation at the time of the inspection. Based on the size of excavation, more than 10 cubic yards of soil has been removed from the location. Screening indicated impacts were still present in two sidewall samples and one floor sample. The screened samples were submitted for laboratory analysis.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:				
Type				
Comment:	Orange construction fencing up at time of inspection.			
Corrective Action:				Date:

Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 272093 Type: WELL API Number: 001-09503 Status: SI Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other			
Comment	All previously excavated soils removed from location.			
Corrective Action				Date:

Spill/Remediation:

Comment:	Based on the size of excavation, more than 10 cubic yards of soil has been removed from the location and disposed of off site. Screening indicated impacts were still present in two sidewall samples and one floor sample. The screened samples were submitted for laboratory analysis.		
Corrective Action:	Per Rule 912.b.(1).E "Operator shall submit a Form 19 spill report for the discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards."	Date:	07/23/2022

Emission Control Burner (ECB):	_____
Comment:	_____
Pilot:	_____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403114089	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810647
691201637	Excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810635
691201638	Impacted soils in situ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810636