

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2022

Submitted Date:

07/22/2022

Document Number:

702400779**FIELD INSPECTION FORM**Loc ID 431789 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465888	TANK BATTERY	AC	07/08/2019		-	lone NE 10 H battery	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate, beginning to fade		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	hog fence		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 20		
Comment:	automation		
Corrective Action:		Date:	
Type: Emission Control Device	# 7		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card indicates that calibration is not current		
Corrective Action:	Comply with Rule 430 Gas Meter Calibration	Date:	08/22/2022
Type: Horizontal Heated Separator	# 7		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 14		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	7	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	230 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares containment with condensate tanks				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	19	400 BBLs	STEEL AST		40.156660,-104.758260	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

API Number
123-36774
123-36779
123-36777

AirsID

API Number	AirsID
------------	--------

123-36780

123-36775

123-36778

123-36776

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 7-22-2022 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: Civitas/Crestone Peak Resources</p> <p>Location name: Lone NE 10H Battery</p> <p>Facility # 465888</p> <p>County: Weld</p> <p>Weather: Clear.</p> <p>Location: .Dry.</p> <p>While there, I observed a tank battery facility, AC at the time of inspection.</p> <p>During this inspection, I observed the following possible compliance issues:</p> <p>430 Calibration: Card in Meter house indicates that calibration is not current, CA date 8-22-2022.</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	07/22/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403114091	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810648
702400780	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810638