

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2022

Submitted Date:

07/21/2022

Document Number:

702500269**FIELD INSPECTION FORM**Loc ID 306819 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone | Email                         | Comment                  |
|------------------|-------|-------------------------------|--------------------------|
| , General        |       | sjninspections@ikavenergy.com | All SW field inspections |
| Labowskie, Steve |       | steve.labowskie@state.co.us   |                          |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 268649      | WELL | PR     | 07/15/2003  | CBM        | 067-08835 | KRAJACK 43-27 2 | PR          |

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |  |  |                  |
|--------------------|--|--|------------------|
| Type               | TANK LABELS/PLACARDS                               |  |                  |
| Comment:           | Produced water tank sign is deteriorated (IMG 03). |  |                  |
| Corrective Action: | Install sign to comply with Rule 605.h.            |  | Date: 08/21/2022 |

Emergency Contact Number:

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | OTHER   |       |  |
| Comment:           | Separator, gas meter run, telemetry, and produced water tank are enclosed by stock panel. |       |  |
| Corrective Action: |   | Date: |  |

**Equipment:**

|                                 |  |       |                 |
|---------------------------------|--|-------|-----------------|
|                                 |  |       | corrective date |
| Type: Flow Line                 | # 2  |       |                 |
| Comment:                        | 3" line from wellhead to separator, line from separator to produced water. |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Gas Meter Run             | # 1  |       |                 |
| Comment:                        | Gas meter calibration is within the last year                              |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Bird Protectors           | # 1  |       |                 |
| Comment:                        | Separator vent stack is screened properly                                  |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Ancillary equipment       | # 1  |       |                 |
| Comment:                        | Telemetry  |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Vertical Heated Separator | # 1  |       |                 |
| Comment:                        |  |       |                 |
| Corrective Action:              |  | Date: |                 |
| Type: Bradenhead                | # 1  |       |                 |
| Comment:                        | Bradenhead is accessible.  |       |                 |
| Corrective Action:              |  | Date: |                 |

**Tanks and Berms:**

|  |   |           |           |         |                       |  |
|--|---|-----------|-----------|---------|-----------------------|--|
| Contents                                       | # | Capacity  | Type      | Tank ID | SE GPS                |  |
| PRODUCED WATER                                 | 1 | <100 BBLs | PBV STEEL |         | 37.155938,-107.704321 |  |
| Comment: Partially buried produced water tank. |   |           |           |         |                       |  |
| Corrective Action:                             |   |           |           |         | Date:                 |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 95 bbl   |  |
| Other (Type)     | cone top |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |            |                       |            |
|----------------------|------------|-----------------------|------------|
| Facility ID: 268649  | Type: WELL | API Number: 067-08835 | Status: PR |
| Insp. Status: PR     |            |                       |            |
| Producing Well       |            |                       |            |
| Comment:             |            |                       |            |
| Corrective Action:   |            | Date:                 |            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Compaction              | Pass                  |               |                          |         |
| Compaction       | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403113282    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810084">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810084</a> |
| 702500270    | Photo doc            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810080">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810080</a> |