

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2022

Submitted Date:

08/08/2022

Document Number:

688312868

FIELD INSPECTION FORM

Loc ID 309662 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10722
Name of Operator: KTM OPERATING LLC
Address: 2851 JOHNSTON ST PMB 550
City: LAFAYETTE State: LA Zip: 70503

Findings:

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Vincent, Kenny	(337) 654-9404	kvincent@reagan.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300642	WELL	SI	03/01/2019	OW	073-06370	CRAIG 4-33	TA

General Comment:

Reinspection

Last MIT: Document #401282024 300642 05-073-06370 CRAIG - 4-33 5/22/2017. SI/TA since 4/1/2015.
Warning Letter: Document #403071830 WARN -00 IN PROCESS 6/8/2022 6/8/2022 KTM OPERATING LLC.
In WL Form 7s were due but are now through 6/1/2022.
In WL MIT due by 8/31/2022.

Bradenhead at 22 psi and will not blow down. Has been tested by operator and is thermogenic gas. Submit Form 4 for bradenhead remediation.

No sign at well. Access road down hill to location is eroded and near South Rush Creek (see attached photos). Control weeds.

Location					
Lease Road:					
Type	Access				
comment:	Eroding down towards South Rush Creek (see attached photos).				
Corrective Action:	Install or repair required BMPs per Rule 1002.f(2)C.				Date: 08/23/2022
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Per operator, well sign was removed with pumping unit.				
Corrective Action:	Install sign to comply with Rule 605.d.				Date: 08/23/2022
Emergency Contact Number:					
Comment:	<input type="text"/>				Date: _____
Corrective Action:	<input type="text"/>				Date: _____
Good Housekeeping:					
Type	WEEDS				
Comment:	Control weeds at fenced location.				
Corrective Action:	Comply with Rule 606.				Date: 08/23/2022
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:	<input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	LOCATION				
Comment:					
Corrective Action:					Date:
Equipment:					
Type:	Bradenhead	# 1			corrective date
Comment:	Bradenhead will not blow down and was tested as thermogenic gas.				
Corrective Action:	Verify Bradenhead pressure. If pressure is in excess, immediately takes steps outlined in Rule 419.b.(4). Contact COGCC Engineering.				Date: 09/09/2022
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:					Date:
Paint					

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 300642 Type: WELL API Number: 073-06370 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is TA because the pumping unit is removed.

Corrective Action: Per WL: Document #403071830 WARN -00 IN PROCESS 6/8/2022 6/8/2022 KTM OPERATING LLC, MIT is due by 8/31/2022.

Date: 08/31/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688312869	KTM Craig 4-33	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5823917